

PLYWOOD



HSP101
Flooring Plywood®
BS 8203:2017

- Moisture content is very accurate.
- Precise drying in manufacture resulting in a fully stable and conditioned panel.
- No core overlap or gaps creating a high quality surface finish.
- Superior construction makes SP101® much more reliable and stable.
- Very strictly controlled and accurate dimensional tolerances.
- Manufactured to flooring industry standards as defined by BS 8203:2017. SP101 Flooring Plywood® is a fully reliable component for use in the subfloor base construction for all floor coverings.

PLYWOODN'T



Non-compliant Plywood

- Moisture content can vary a lot resulting in distortion.
- Veneer glue bonds are known to fail in flooring applications.
- Core veneer overlaps and gaps are common in most panels and result in poor surface quality and thickness variation.
- Face veneers can be very thin and readily permeable to moisture and adhesives.
- General commercial plywood is not usually manufactured to flooring standards and may cause problems in use.